EXTRANET USER GUIDE

INTRODUCTION

This user guide provides instructions for using MACOM's extranet service to access and download a process development kit (PDK).

FIRST STEPS

LOG IN
Please go to this link: **extranetfr.macom.com**
① Enter your email address and the password that was just sent to you.

FORGOT YOUR PASSWORD
② To reset a lost password, please click on "LOST YOUR PASSWORD?"

INTERFACE
Once logged in, you are on the MACOM extranet interface where you are now able to proceed with your selection.

CHANGE YOUR PASSWORD
③ At the top of the page, please click on your name and select "CHANGE PASSWORD." We recommend that you keep your password secure and not share it with anyone.

LOG OUT
④ To log out, click on your name on top right of the page and click on log out. If you want to return to our website, click on the MACOM logo.

WHAT YOU CAN DO

DOWNLOAD A PDK

To access a PDK, press the blue «DOWNLOAD ZONE» button. You will then have access to one or several processes, each in a distinct folder. You may copy the zip files from the ADS, AWR or Pspice CAD library, as well as the library's installation and user manuals.

UPLOAD YOUR FILES

You can add files to your personal directory by pressing the grey «UPLOAD FILES» button. Click on «BROWSE», select your file and wait for the loading to be completed. Please note, file size is limited to 2048 Mb and only .zip and .7z file extensions are allowed.

FOR SUPPORT

For further information and support please visit: https://www.macom.com/support.